

# Vehicle Condition Report

Brasher's Portland Auto Auction

23585 NE Sandy Blvd.  
Wood Village, OR 97060  
(503) 492-9200

All listings are subject to change without notice. Information is deemed to be reliable, but not guaranteed until announced on the auction block.

## Vehicle Description

### 2011 Chevrolet Tahoe No Trim Badge

|              |                     |          |       |
|--------------|---------------------|----------|-------|
| VIN          | 1GNSK4E09BR351076   |          |       |
| Ext. Color   | Gray                |          |       |
| Int. Color   | Black               | Interior | Cloth |
| Mileage      | 74,315 Actual Miles |          |       |
| Engine       | 5.3L 8-Cylinder Gas |          |       |
| Transmission | Automatic           |          |       |



## Auction Data

|           |                    |       |      |
|-----------|--------------------|-------|------|
| Sale Date | To Be Announced    |       |      |
| Run #     | To Be Announced    | Inv # | 7721 |
| Consignor | GSA FLEET SERVICES |       |      |

## Declarations

|          |                     |
|----------|---------------------|
| Warranty | GSA Regular Terms   |
| Mileage  | 74,315 Actual Miles |
| Title    | Clear Title         |

## Equipment

- 4 Wheel Drive
- Air Conditioning
- Trip Counter
- Anti Lock Brakes
- Keyless Entry
- Rear Defog
- Automatic Transmission
- Electronic Traction Control
- Dual and Side Air Bags
- Steel Wheels
- Towing Package
- Power Steering
- 8 Cylinder Gas
- Power Windows
- Cruise Control
- Tilt Steering Wheel
- Hard Top
- Power Brakes
- 5 Passenger
- Power Locks
- Dual Air Thermostats
- AM/FM CD
- Rear Wiper
- Electric Mirrors

## Damage Descriptions (CR completed on 9/10/2015 by SKYLAR FICKLIN)

| #                     | Location     | Damage Action | Severity           | Parts \$ | Other \$ | Repair hours | Paint hours | Part hours | Total |
|-----------------------|--------------|---------------|--------------------|----------|----------|--------------|-------------|------------|-------|
| <b>Front</b>          |              |               |                    |          |          |              |             |            |       |
| 1                     | Front Bumper | Chips         | Multiple Instances |          |          |              |             |            | --    |
| 2                     | Hood         | Chips         | Multiple Instances |          |          |              |             |            | --    |
| <b>Front Subtotal</b> |              |               |                    | --       | --       | --           | --          | --         | --    |

# 2011 Chevrolet Tahoe No Trim Badge

VIN: 1GNSK4E09BR351076

Inv#: 7721

|                 | #                        | Location           | Damage Action | Severity           | Parts \$ | Other \$ | Repair hours | Paint hours | Part hours | Total |
|-----------------|--------------------------|--------------------|---------------|--------------------|----------|----------|--------------|-------------|------------|-------|
| <b>Interior</b> |                          |                    |               |                    |          |          |              |             |            |       |
|                 | 3                        | Headlining         | Dirty         | Multiple Instances |          |          |              |             |            | --    |
|                 |                          |                    |               |                    |          |          |              |             |            | --    |
|                 | 4                        | Interior           | Dirty         | Multiple Instances |          |          |              |             |            | --    |
|                 |                          |                    |               |                    |          |          |              |             |            | --    |
|                 | 5                        | Seats              | Dirty         | Multiple Instances |          |          |              |             |            | --    |
|                 |                          |                    |               |                    |          |          |              |             |            | --    |
|                 | 6                        | Vinyl Floor        | Dirty         | Multiple Instances |          |          |              |             |            | --    |
|                 |                          |                    |               |                    |          |          |              |             |            | --    |
|                 | <b>Interior Subtotal</b> |                    |               |                    | --       | --       | --           | --          | --         | --    |
|                 |                          |                    |               |                    |          |          | --           | --          | --         | --    |
| <b>Left</b>     |                          |                    |               |                    |          |          |              |             |            |       |
|                 | 7                        | Left Front Door    | Scratched     | Multiple Instances |          |          |              |             |            | --    |
|                 |                          |                    |               |                    |          |          |              |             |            | --    |
|                 | 8                        | Left Front Fender  | Scratched     | Multiple Instances |          |          |              |             |            | --    |
|                 |                          |                    |               |                    |          |          |              |             |            | --    |
|                 | 9                        | Left Qtr Panel     | Scratched     | Multiple Instances |          |          |              |             |            | --    |
|                 |                          |                    |               |                    |          |          |              |             |            | --    |
|                 | <b>Left Subtotal</b>     |                    |               |                    | --       | --       | --           | --          | --         | --    |
|                 |                          |                    |               |                    |          |          | --           | --          | --         | --    |
| <b>Rear</b>     |                          |                    |               |                    |          |          |              |             |            |       |
|                 | 10                       | Rear Bumper        | Scratched     | Multiple Instances |          |          |              |             |            | --    |
|                 |                          |                    |               |                    |          |          |              |             |            | --    |
|                 | <b>Rear Subtotal</b>     |                    |               |                    | --       | --       | --           | --          | --         | --    |
|                 |                          |                    |               |                    |          |          | --           | --          | --         | --    |
| <b>Right</b>    |                          |                    |               |                    |          |          |              |             |            |       |
|                 | 11                       | Right Front Door   | Light Scratch | Multiple Instances |          |          |              |             |            | --    |
|                 |                          |                    |               |                    |          |          |              |             |            | --    |
|                 | 12                       | Right Front Fender | Light Scratch | Multiple Instances |          |          |              |             |            | --    |
|                 |                          |                    |               |                    |          |          |              |             |            | --    |
|                 | 13                       | Right Qtr Panel    | Scratched     | Multiple Instances |          |          |              |             |            | --    |
|                 |                          |                    |               |                    |          |          |              |             |            | --    |
|                 | 14                       | Right Rear Door    | Scratched     | Multiple Instances |          |          |              |             |            | --    |
|                 |                          |                    |               |                    |          |          |              |             |            | --    |
|                 | <b>Right Subtotal</b>    |                    |               |                    | --       | --       | --           | --          | --         | --    |
|                 |                          |                    |               |                    |          |          | --           | --          | --         | --    |

# 2011 Chevrolet Tahoe No Trim Badge

VIN: 1GNSK4E09BR351076

Inv#: 7721

| # | Location | Damage Action | Severity | Parts \$ | Other \$ | Repair hours | Paint hours | Part hours | Total |
|---|----------|---------------|----------|----------|----------|--------------|-------------|------------|-------|
|---|----------|---------------|----------|----------|----------|--------------|-------------|------------|-------|

## Structural

|    |                 |      |      |  |  |  |  |  |    |
|----|-----------------|------|------|--|--|--|--|--|----|
| 15 | Left Front Rail | Dent | None |  |  |  |  |  | -- |
|----|-----------------|------|------|--|--|--|--|--|----|

Comment: Am Holes Drilled In Front Rails

|    |                  |      |      |  |  |  |  |  |    |
|----|------------------|------|------|--|--|--|--|--|----|
| 16 | Right Front Rail | Dent | None |  |  |  |  |  | -- |
|----|------------------|------|------|--|--|--|--|--|----|

Comment: Am Holes Drilled In Front Rails

Structural Subtotal

|    |    |    |    |    |    |
|----|----|----|----|----|----|
| -- | -- | -- | -- | -- | -- |
|    |    | -- | -- | -- | -- |

Total

|    |    |    |    |    |    |
|----|----|----|----|----|----|
| -- | -- | -- | -- | -- | -- |
|    |    | -- | -- | -- | -- |

## Tires

| Region      | Brand   | Size | Tread Depth       |
|-------------|---------|------|-------------------|
| Left Front  | RADIAL  | /-   | Average (Average) |
| Left Rear   | RADIAL  | /-   | Average (Average) |
| Right Front | RADIAL  | /-   | Average (Average) |
| Right Rear  | RADIAL  | /-   | Average (Average) |
| Spare       | FACTORY | /-   | Average (Average) |

## Miscellaneous

|                          |    |
|--------------------------|----|
| Coolant level            | OK |
| Interior odor            | OK |
| Oil level                | OK |
| Transmission fluid level | OK |

## Images



## 2011 Chevrolet Tahoe No Trim Badge

VIN: 1GNSK4E09BR351076

Inv#: 7721

